# Light Meter with Memory

## Large LCD with advanced illuminance functions and features

- Wide measurement range to 99,990 fc (999,900 lux) with resolution of 0.001 fc & 0.01 lux
- Luminous intensity (candela) calculations
- Store and recall up to 50 measurements, includes relative or real-time clock stamp
- Ripple function excludes the effect of stray light from the primary lightsource measurement
- Auto power-off with disable feature
- Multiple point average function
- Timed-Hold, relative in absolute value or % deviation, and comparator function with high/low alarms
- Cosine- and color-corrected, CNS 5119 Class II

01598-10

| SPECIFICATIONS | |
|---|---|
| Fc range | 9.999, 99.99, 999.9, 9,999, 99,990 |
| Lux range | 99.99, 999.9, 9999, 99,990, 999,900 |
| Max resolution | 0.001 fc / 0.01 lux |
| Accuracy | ±3% |
| Display | Backlit LCD |
| Dimensions (W x H x D) | 2²⁷⁄₃₂" x 5²⁹⁄₃₂" x 1⁹⁄₃₂" (72 x 150 x 33 mm) |
| Power | Six AAA batteries |

**What's included:** Light sensor, built-in stand, protective cover with 36" (0.9 m) cable, carrying case, protective holster, and six AAA batteries.

| Catalog No. | Model No. | Description | |
|---|---|---|---|
| TS-01598-10 | EA33 | EasyView light meter with memory | |
| **Accessories** | | | |
| TS-09386-00 | — | Replacement batteries, AAA. 12/pk | |
| **TS-17111-44** | **—** | **NIST-traceable calibration with data** | |

# Pocket Footcandle Light Meter

## Measures up to 2000 fc for basic lighting applications

- Easy-to-operate footcandle light meter with two ranges
- Convenient pocket-size design
- Overrange indication
- Cosine- and color-corrected measurements

| SPECIFICATIONS | |
|---|---|
| Fc range | 200, 2000 |
| Max resolution | 0.1 fc |
| Accuracy | ±5% |
| Display | 2000 count LCD |
| Dimensions (W x H x D) | 2¾" x 5¼" x 1" (70 x 131 x 25 mm) |
| Power | One 9 V battery |

**What's included:** Light sensor and protective cover with 47" (1.2 m) cable, built-in stand, and one 9 V battery.

40410-10

| Catalog No. | Model No. | Description | |
|---|---|---|---|
| TS-40410-10 | 401027 | Pocket footcandle light meter | |
| **Accessories** | | | |
| TS-09386-04 | — | Replacement batteries, 9 V. 4/pk | |
| **TS-17111-44** | **—** | **NIST-traceable calibration with data** | |