Digital and analog display of light in fc or lux

- Relative mode indicates change in light levels
- Peak mode captures highest reading
- Remote light sensor on 12" (305 mm) coiled cable expandable to 24" (609 mm)
- Utilizes precision photo diode and color-correction filter
- Cosine- and color-corrected measurements
- Min/Max feature stores maximum and minimum readings
- Data Hold freezes reading in the display
- Large LCD display with analog bar graph
- Backlight for readings in low light levels



What's included: Light sensor with protective cover, protective holster, and 9 V battery.

	· ·	•
Catalog No.	Model No.	Description
TS-50520-93	LT300	Light meter
Accessories		
TS-09386-04	_	Replacement batteries, 9 V. 4/pk
TS-17111-44	_	NIST-traceable calibration with data

SPECIFICATIONS	
Fc range	0.1 to 20,000
Lux range	0.1 to 200,000
Max resolution	0.01 fc / lux
Accuracy	\pm 5% of reading + 0.5% full scale
Display	Backlit LCD
Dimensions (W x H x D)	2 ¹⁵ / ₁₆ " x 5 ⁷ / ₈ " x 1 ⁹ / ₁₆ " (75 x 150 x 40 mm)
Power	One 9 V battery

Deluxe Light Meters

Use for high-intensity measurements up to 40,000 fc and 400,000 lux

- Compact and rugged design features large display and bar graph
- Wide measuring ranges:
 - EA30: 40,000 fc in 4 ranges and 400,000 lux in 5 ranges
 - EA31: 20,000 fc in 4 ranges and 20,000 lux in 4 ranges
- Min/Max and Data Hold
- Large display with bar graph
- Cosine- and color-corrected measurements
- Auto power-off; low battery and overrange indication
- Utilizes precision silicon photodiode sensor with 39" (1 m) coiled cable for easy storage

Additional Features for Model EA30

- Peak hold captures short light pulses to 100 µsec
- Relative function for zero or difference from reference value



SPECIFICATIONS				
Model No.	EA30	EA31		
Fc range	40, 400, 4000, 40,000	20, 200, 2000, 20,000		
Lux range	40, 400, 4000, 40,000, 400,000	20, 200, 2000, 20,000		
Max resolution	0.01 fc/lux			
Accuracy	$\pm 3\%$ rdg + 0.5% F.S.			
Dimensions (W x H x D)	2 ²⁷ / ₃₂ " x 5 ²⁹ / ₃₂ " x 1 ⁹ / ₃₂ " (72 x 150 x 33 mm)			
Power	Six AAA batteries			

What's included Remote sensor with protective cover, built-in stand, protective holster, and six AAA batteries.

Catalog No.	Model No.	Description
TS-01598-65	EA30	Deluxe high-intensity light meter
TS-50520-91	EA31	Deluxe light meter
Accessories		
TS-09386-00	_	Replacement batteries, AAA. 12/pk
TS-17111-44	_	NIST-traceable calibration with data